

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 17, 2007

Blake Crockett, Administrator Warren House 1301 Bennett Street Burley, ID 83318

License #: RC-579

Dear:

On September 25, 2007, a Fire Life Safety Survey was conducted at Warren House. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

EM/li

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Eider Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 5, 2007

Blake Crockett, Administrator Warren House 1301 Bennett Street Burley, ID 83318

Dear Mr. Crockett:

On September 25, 2007, a Fire Life Safety Survey was conducted at Warren House. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 25, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/li

Enclosure

PRINTED: 10/02/2007 FORM APPROVED

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - ENTIRE BUILDIGN A. BUILDING B. WING 13R579 09/25/2007 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1301 BENNETT ST **WARREN HOUSE BURLEY, ID 83318** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID ID (X5) COMPLETE DATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on September 25, 2007. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction Program

Bureau of Facility Standards

TITLE

(X6) DATE

BKW321



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name * / /			Physical Address	Phone Number	Phone Number		
Facility Name House			Physical Address 301 Bennett Street City Bar by Survey Type	115 Code - 77 - 82/2			
Administrator			City	ZIP Code			
Tommie Dean			Barley	Bar ley 83318			
Administrator Tommic Dean Survey Team Leader E. Mun Lell			Survey Type	Survey Date	Survey Date		
			FCS	15/07			
	-CORE ISSU	=S		1			
ITEM #	RULE# 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE	
7	405,03	Medical Course:	Ventilation fan in organ operable. The fan would no 3000 ft3).	sterage.			
		11.00	associate The fam would be	+ +1000		55.64.66	
		10000 (13)	2 (13)	1 1 2 7 7 7			
		0m. (200 + 1 '- "	7000 tt).				
					A.A.		
					***************************************	0.000	
<u> </u>							
<u> </u>	-					100000	
						242444607866	
						1000000000	

						9.0000	
	**************************************				same and a second		
						04.55.60	

BFS-686 March 2006

Response Required Date

Signature of Facility Representative

Date Signed